

Under Review Notification

Raised By: Alan Stocker

Product #: D350-591-213

Date: 15.12.17

Product Name: Step

Part Number (D-Part and 9-Digit)	Drawing/Document & Current Affected Revision	"Y" or "N" Required for Each Part							Reserved ECN Log Number	Instructions Relevant to Each Part
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	In-Work Stock	IPP Under Review	Product Specifications Under Review		
D350-591-213	G	Y	Y	N	Y	Y	Y	N	15-656	
D350-591-214	G	Y	Y	N	Y	N	Y	N	15-656	
D350-591-215	G	Y	Y	N	Y	N	Y	N	15-656	
D350-591-216	G	Y	Y	N	Y	N	Y	N	15-656	
D3078-041	A	Y	Y	N	Y	N	Y	N	15-656	
D3078-042	A	Y	Y	N	Y	N	Y	N	15-656	
D3168-041	A	Y	Y	N	Y	N	Y	N	15-656	
D3168-042	A	Y	Y	N	Y	N	Y	N	15-656	

Description of Issue:

Cracking at aft attach point reported by customer helistream see CIR15-44

Ship remaining D350-591-213/-214 Kit to Helistream no charge as a temporary Fix do not manufacture anymore D3078 -041/-043 or D3116-041/-043 at Rev A.